



Acumen Laboratory and Testing Limited

Flat/Rm D, 12/F, Ford Glory Plaza, Nos. 37-39 Wing Hong Street, Cheung Sha Wan, Kowloon, Hong Kong
 Tel: (852) 2333 6823 Fax: (852) 2333 1316

Appendix - Quality Control Summary Table

Project Name: Hung Shui Kiu/Ha Tsuen New Development Area Stage 1 Works

		Method Blank Report		Duplicate Report			Sample Spike Report		Pass / Fail
		MDL	Result	Original Result	Duplicate Result	RPD	Spike concentration	Spike Recovery	
Sampling Date	Job No. Unit	mg/L	mg/L	mg/L	mg/L	%	mg/L	%	/
02/08/2023	R231133	0.22	0.05	5.12	4.82	6.0	10	93.1	Pass
04/08/2023	R231134	0.22	0.08	5.09	5.33	-4.6	10	92.5	Pass
08/08/2023	R231180	0.22	0.06	5.70	5.88	-3.1	10	96.2	Pass
10/08/2023	R231205	0.22	0.05	4.04	3.82	5.6	10	91.2	Pass
12/08/2203	R231206	0.22	0.07	3.41	3.64	-6.5	10	92.4	Pass
15/08/2023	R231235	0.22	0.06	5.06	4.78	5.7	10	96.6	Pass
17/08/2023	R231251	0.22	0.08	4.93	5.17	-4.8	10	91.5	Pass
19/08/2023	R231252	0.22	0.06	4.50	4.78	-6.0	10	93.6	Pass
21/08/2023	R231301	0.22	0.07	4.21	4.07	3.4	10	90.9	Pass
23/08/2023	R231302	0.22	0.07	4.96	4.80	3.3	10	94.4	Pass
25/08/2023	R231303	0.22	0.09	5.13	5.44	-5.9	10	93.7	Pass
29/08/2023	R231341	0.22	0.07	5.72	5.98	-4.4	10	95.0	Pass
30/08/2023	R231342	0.22	0.05	5.50	5.32	3.3	10	92.1	Pass
31/08/2023	R231343	0.22	0.06	4.24	4.10	3.4	10	96.0	Pass